

Structures Group Chairperson's Factual Report

APPENDIX H
Photographs

NTSB Airplane Accident Case No. DCA00MA006
60 miles south of Nantucket, Massachusetts
October 31, 1999
Boeing 767-336, SU-GAP



Photo #1 - Fuselage Section 41



Photo #2 - Fuselage Section 41 View of
Cockpit Window Frames



Photo #3 - Fuselage Section 43



Photo #4 - Fuselage Section 43



Photo #5 - Fuselage Section 45



Photo #6 - Fuselage Section 46



Photo #7 - Fuselage Section 46 - Window Belt



Photo #8 - Fuselage Section 48



Photo #9 - Miscellaneous Fuselage (area 1)



Photo #10 - Miscellaneous Fuselage (area 2)



Photo #11 - Miscellaneous Fuselage (area 3)



Photo #12 - Doors (general)



Photo #13 - Overview of Recovered Wing



Photo #14 - Wing Leading Edge



Photo #15 - Wing Leading Edge - Section 14



Photo #16 - Wing Center Section - Section 11



Photo #17 - Wing Box - Section 12



Photo #18 - Wing Trailing Edge - Section 13



Photo #19 - Landing Gear Beams



Photo #20 - Engine Pylon - Engine #2



Photo #21 - Engine Pylon - Engine #1



Photo #22 - Horizontal Stabilizer



Photo #23 - Vertical Fin



Photo #24 - Miscellaneous Tail



Photo #25 - Main Landing Gear



Photo #26 - Nose Landing Gear



Photo #27 - Tail Skid